

## **List of Reference Characters**

	Α	amplitude
5	D	data input of Q
	f	frequency
	t	time
	PNCode	pseudo-noise code
	Q	shift register
10	Q1-Qn	stages of shift register
	Sender A	transmission signal generator
	Sender B	transmission signal generator
	Sender C	transmission signal generator
	TAKT	clocking rate for control of pulse repetition
15		frequency
	10	PN-code generator
	12	XOR-gate
	14	switch
20	16	switch





0 1000 2000 3000 4000 Fig. 10

-100 500 Fig. 9

1000 1500 2000